

**Schedule of Accreditation**  
 issued by  
**United Kingdom Accreditation Service**

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

 <b>0291</b> <b>Type C</b> <b>Inspection Body</b> <small>Accredited to ISO/IEC 17020:2012</small>	<p style="text-align: center;"><b>Bradley Environmental Consultants Ltd</b></p> <p style="text-align: center;"><b>Issue No: 018   Issue date: 18 July 2025</b></p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%;"> <b>20 Stourbridge Road</b>  <b>Halesowen</b>  <b>West Midlands</b>  <b>B63 3US</b> </td><td style="width: 50%;"> <b>Contact: Mr R Bridgewater</b>  <b>Tel: +44 (0)121 550 0224</b>  <b>Fax: +44 (0)121 550 0641</b>  <b>E-Mail: rbridgewater@bradley-enviro.co.uk</b>  <b>Website: www.bradley-enviro.co.uk</b> </td></tr> </table>		<b>20 Stourbridge Road</b> <b>Halesowen</b> <b>West Midlands</b> <b>B63 3US</b>	<b>Contact: Mr R Bridgewater</b> <b>Tel: +44 (0)121 550 0224</b> <b>Fax: +44 (0)121 550 0641</b> <b>E-Mail: rbridgewater@bradley-enviro.co.uk</b> <b>Website: www.bradley-enviro.co.uk</b>
<b>20 Stourbridge Road</b> <b>Halesowen</b> <b>West Midlands</b> <b>B63 3US</b>	<b>Contact: Mr R Bridgewater</b> <b>Tel: +44 (0)121 550 0224</b> <b>Fax: +44 (0)121 550 0641</b> <b>E-Mail: rbridgewater@bradley-enviro.co.uk</b> <b>Website: www.bradley-enviro.co.uk</b>			
<small>Inspection performed at/from the locations specified below</small>				

**Locations covered by the organisation and their relevant activities**

Location details	Activity	Location code
<b>Address</b> 20 Stourbridge Road Halesowen West Midlands B63 3US	<b>Local contact</b> Mr R Bridgewater  Tel: +44 (0)121 550 0224 Fax: +44 (0)121 550 0641 Email: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	<u>Support Functions:</u> Quality Management including document control, auditing and quality control  <u>Asbestos:</u> Surveying
<b>Address</b> Parkway House Wakefield Road Ossett West Yorkshire WF5 9JD	<b>Local contact</b> Mr R Bridgewater  Tel: +44 (0)1924 274777 Fax: +44 (0)1924 283620 Email: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	<u>Asbestos:</u> Surveying
<b>Address</b> North West Office Constellation House Lockheed Court Amy Johnson Way Blackpool FY4 2RN	<b>Local contact</b> Mr R Bridgewater  Tel: +44 (0)1253 405396 Fax: +44 (0)1253 402426 Email: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	<u>Asbestos:</u> Surveying
<b>Address</b> Unit 11 Geddes House Kirkton Road North Livingston EH54 6GU	<b>Local contact</b> Mr R Bridgewater  Tel: +44 (0)1745 585587 Fax: +44 (0) 1745 584974 Email: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	Hygiene and Health



0291

Type C  
Inspection Body

Accredited to  
ISO/IEC 17020:2012

**Schedule of Accreditation**  
issued by  
**United Kingdom Accreditation Service**  
2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

**Bradley Environmental Consultants Ltd**

**Issue No: 018      Issue date: 18 July 2025**

Inspection performed by the Organisation at/from the locations specified

Location details	Activity	Location code
<b>Address</b> Unit 10 ViewPoint Boxley Road Penenden Heath Maidstone Kent ME14 2DZ	<b>Local contact</b> Mr R Bridgewater  Tel: +44 (0)121 550 0224 Fax: +44 (0)121 550 0641 Email: <a href="mailto:rbridgewater@bradley-enviro.co.uk">rbridgewater@bradley-enviro.co.uk</a> Website: <a href="http://www.bradley-enviro.co.uk">www.bradley-enviro.co.uk</a>	Hygiene and Health  H



0291  
Type C  
Inspection Body

Accredited to  
ISO/IEC 17020:2012

**Schedule of Accreditation**  
issued by  
**United Kingdom Accreditation Service**  
2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

**Bradley Environmental Consultants Ltd**

**Issue No: 018      Issue date: 18 July 2025**

Inspection performed by the Organisation at/from the locations specified

**DETAIL OF ACCREDITATION**

Field of Inspection	Type and Range of Inspection	Methods and Procedures	Location Code
Surveying for asbestos in premises	Management survey: (domestic, commercial and industrial premises)  Refurbishment and demolition survey: (domestic, commercial and industrial premises)  Re-inspection of identified or suspected asbestos containing material in surveyed premises	Health and Safety Executive Asbestos: The survey guide (HSG 264:2012)  Documented in-house procedure - Inspection, section 20 and appendix 6, Quality Manual  Documented in-house procedure - Inspection, section 20 and appendix 6, Quality Manual  Documented in-house procedure - Inspection, section 20 and appendix 6, Quality Manual (based on guidance documented in Inspection, Appendix 5 of HSG 227 (2004))	A, B, C, F, H  A, B, C, F, H  A, B, C, F, H

END