


Schedule of Accreditation

issued by

United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

 <p>1155</p> <p>Accredited to ISO/IEC 17025:2017</p>	Bradley Environmental Consultants Ltd	
	Issue No: 035 Issue date: 12 August 2024	
20 Stourbridge Road Halesowen West Midlands B63 3US	Contact: Mr R Bridgewater Tel: +44 (0)121 550 0224 Fax: +44 (0)121 550 0641 E-Mail: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	
Testing performed by the Organisation at the locations specified below		

Locations covered by the organisation and their relevant activities

Laboratory locations:

Location details	Activity	Location code
<p>Address 20 Stourbridge Road Halesowen West Midlands B63 3US</p> <p>Contact: Mr R Bridgewater Tel: +44 (0)121 550 0224 Fax: +44 (0)121 550 0641 E-Mail: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk</p>	Health and Hygiene Head Office Asbestos – All Support Functions	A
<p>Address Parkway House Wakefield Road Ossett West Yorkshire WF5 9JD</p> <p>Local contact Mr R Bridgewater Tel: +44 (0)1924 274777 Fax: +44 (0)1924 283620 Email: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk</p>	Health and Hygiene Asbestos – Support Functions: <ul style="list-style-type: none"> • <i>Contract Review</i> • <i>Scheduling</i> • <i>Personnel</i> • <i>Equipment</i> • <i>Measurement Traceability</i> • <i>Reporting</i> 	B
<p>Address Constellation House Shorebury Point Amy Johnson Way Blackpool FY4 2RN</p> <p>Local contact Mr R Bridgewater Tel: +44 (0)1253 405396 Fax: +44 (0)1253 402426 E-Mail: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk</p>	Health and Hygiene Asbestos – Support Functions: <ul style="list-style-type: none"> • <i>Contract Review</i> • <i>Scheduling</i> • <i>Personnel</i> • <i>Equipment</i> • <i>Measurement Traceability</i> • <i>Reporting</i> 	C



1155
Accredited to
ISO/IEC 17025:2017

Schedule of Accreditation
issued by
United Kingdom Accreditation Service
2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

Bradley Environmental Consultants Ltd
Issue No: 035 Issue date: 12 August 2024

Testing performed by the Organisation at the locations specified

Location details	Activity	Location code	
Address 85A Bowen Court St Asaph Business Park St Asaph LL17 0JE	Local contact Mr R Bridgewater Tel: +44 (0)1745 585587 Fax: +44 (0) 1745 584974 E-Mail: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	Health and Hygiene Asbestos – Support Functions: <ul style="list-style-type: none">• <i>Contract Review</i>• <i>Scheduling</i>• <i>Personnel</i>• <i>Equipment</i>• <i>Measurement Traceability</i>• <i>Reporting</i>	D
Address Unit 16 Geddes House Kirkton Road North Livingston EH54 6GU	Local contact Mr R Bridgewater Tel: +44 (0)1745 585587 Fax: +44 (0) 1745 584974 E-Mail: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	Health and Hygiene Asbestos – Support Functions: <ul style="list-style-type: none">• <i>Contract Review</i>• <i>Scheduling</i>• <i>Personnel</i>• <i>Equipment</i>• <i>Measurement Traceability</i>• <i>Reporting</i>	F

Site activities performed away from the locations listed above:

Location details	Activity	Location code
Client Premises	Health and Hygiene	G
Mobile Testing Laboratories	Health and Hygiene	E



1155
Accredited to
ISO/IEC 17025:2017

Schedule of Accreditation
issued by
United Kingdom Accreditation Service
2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

Bradley Environmental Consultants Ltd
Issue No: 035 **Issue date:** 12 August 2024

Testing performed by the Organisation at the locations specified

DETAIL OF ACCREDITATION


Materials/Products tested	Type of test/Properties measured/Range of measurement	Standard specifications/ Equipment/Techniques used	Location Code
ASBESTOS FIBRES IN AIR	<u>Health and Hygiene</u>	Health and Safety Executive - Asbestos: The Analysts' Guide (HSG 248) – 2021	
	Sampling of air for fibre counting	Documented In-House Method, appendix 6, Quality Manual, based on HSG 248	A, B, C, F, G
	Fibre counting	Documented In-House Method, appendix 6m Quality Manual, Membrane Filter Method using Phase Contrast Microscopy (PCM) based on HSG 248	A, B, C, E, F
ASBESTOS IN BULK MATERIALS including materials and products suspected of containing asbestos	4 Stage Clearance Process	Documented In-House Method, appendix 6, Quality Manual, Membrane Filter Method using Phase Contrast Microscopy (PCM) based on HSG 248	A, B, C, F, G
	Sampling of bulk materials for subsequent identification of asbestos	Documented In-House Method, appendix 6, Quality Manual, based on HSG 248	A, B, C, F, G
	Identification of: Amosite Chrysotile Crocidolite Fibrous Actinolite Fibrous Anthophyllite Fibrous Tremolite	Documented In-House Method, appendix 7, Quality Manual, using stereo-microscopy, polarised light optical microscopy and dispersion staining based on HSG 248	A, B, C, D
END			

Schedule of Accreditation

issued by

United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

 <p>0291 Type C Inspection Body</p> <p>Accredited to ISO/IEC 17020:2012</p>	Bradley Environmental Consultants Ltd	
	Issue No: 016 Issue date: 13 June 2024	
20 Stourbridge Road Halesowen West Midlands B63 3US	Contact: Mr R Bridgewater Tel: +44 (0)121 550 0224 Fax: +44 (0)121 550 0641 E-Mail: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	
Inspection performed at/from the locations specified below		

Locations covered by the organisation and their relevant activities

Location details	Activity	Location code	
Address 20 Stourbridge Road Halesowen West Midlands B63 3US	Local contact Mr R Bridgewater Tel: +44 (0)121 550 0224 Fax: +44 (0)121 550 0641 Email: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	Support Functions: Quality Management including document control, auditing and quality control Asbestos: Surveying	A
Address Parkway House Wakefield Road Ossett West Yorkshire WF5 9JD	Local contact Mr R Bridgewater Tel: +44 (0)1924 274777 Fax: +44 (0)1924 283620 Email: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	Asbestos: Surveying	B
Address North West Office Constellation House Lockheed Court Amy Johnson Way Blackpool FY4 2RN	Local contact Mr R Bridgewater Tel: +44 (0)1253 405396 Fax: +44 (0)1253 402426 Email: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	Asbestos: Surveying	C
Address Unit 16 Geddes House Kirkton Road North Livingston EH54 6GU	Local contact Mr R Bridgewater Tel: +44 (0)1745 585587 Fax: +44 (0) 1745 584974 E-Mail: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	Hygiene and Health	F



0291

Type C
Inspection Body

Accredited to
ISO/IEC 17020:2012

Schedule of Accreditation
issued by
United Kingdom Accreditation Service
2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

Bradley Environmental Consultants Ltd

Issue No: 016 Issue date: 13 June 2024

Inspection performed by the Organisation at/from the locations specified

DETAIL OF ACCREDITATION

Field of Inspection	Type and Range of Inspection	Methods and Procedures	Location Code
Surveying for asbestos in premises	Management survey: (domestic, commercial and industrial premises)	Health and Safety Executive Asbestos: The survey guide (HSG 264:2012) Documented in-house procedure - Inspection, section 20 and appendix 6, Quality Manual	A, B, C, F
	Refurbishment and demolition survey: (domestic, commercial and industrial premises)	Documented in-house procedure - Inspection, section 20 and appendix 6, Quality Manual	A, B, C, F
	Re-inspection of identified or suspected asbestos containing material in surveyed premises	Documented in-house procedure - Inspection, section 20 and appendix 6, Quality Manual (based on guidance documented in Inspection, Appendix 5 of HSG 227 (2004))	A, B, C, F
END			