


Schedule of Accreditation

issued by

United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

| | | |
|---|--|--|
|  <p>0291 Type C Inspection Body</p> <p>Accredited to ISO/IEC 17020:2012</p> | Bradley Environmental Consultants Ltd | |
| | Issue No: 015 Issue date: 22 September 2021 | |
| | 20 Stourbridge Road Halesowen West Midlands B63 3US | Contact: Mr R Bridgewater Tel: +44 (0)121 550 0224 Fax: +44 (0)121 550 0641 E-Mail: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk |
| Inspection performed at/from the locations specified below | | |

Locations covered by the organisation and their relevant activities

| Location details | Activity | Location code | |
|---|--|---|---|
| Address 20 Stourbridge Road Halesowen West Midlands B63 3US | Local contact Mr R Bridgewater Tel: +44 (0)121 550 0224 Fax: +44 (0)121 550 0641 Email: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk | Support Functions: Quality Management including document control, auditing and quality control Asbestos: Surveying | A |
| Address Parkway House Wakefield Road Ossett West Yorkshire WF5 9JD | Local contact Mr R Bridgewater Tel: +44 (0)1924 274777 Fax: +44 (0)1924 283620 Email: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk | Asbestos: Surveying | B |
| Address North West Office Constellation House Lockheed Court Amy Johnson Way Blackpool FY4 2RN | Local contact Mr R Bridgewater Tel: +44 (0)1253 405396 Fax: +44 (0)1253 402426 Email: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk | Asbestos: Surveying | C |
| Address 85A Bowen Court St Asaph Business Park St Asaph LL17 0JE | Local contact Mr R Bridgewater Tel: +44 (0) 1745 585587 Fax: +44 (0) 1745 584974 E-Mail: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk | Asbestos: Surveying | D |



0291

Type C
Inspection Body

Accredited to
ISO/IEC 17020:2012

Schedule of Accreditation
issued by
United Kingdom Accreditation Service
2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

Bradley Environmental Consultants Ltd
Issue No: 015 Issue date: 22 September 2021

Inspection performed by the Organisation at/from the locations specified

| | | | |
|---|---|--------------------|---|
| Address Unit 16 Geddes House Kirkton Road North Livingston EH54 6GU | Local contact Mr R Bridgewater Tel: +44 (0)1745 585587 Fax: +44 (0) 1745 584974 E-Mail: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk | Hygiene and Health | F |
|---|---|--------------------|---|



0291
Type C
Inspection Body
 Accredited to
 ISO/IEC 17020:2012

Schedule of Accreditation
 issued by
United Kingdom Accreditation Service
 2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

Bradley Environmental Consultants Ltd
Issue No: 015 Issue date: 22 September 2021

Inspection performed by the Organisation at/from the locations specified

DETAIL OF ACCREDITATION

| Field of Inspection | Type and Range of Inspection | Methods and Procedures | Location Code |
|------------------------------------|--|--|------------------|
| Surveying for asbestos in premises | Management survey: (domestic, commercial and industrial premises) | Health and Safety Executive Asbestos: The survey guide (HSG 264:2012) Documented in-house procedure - Inspection, section 20 and appendix 6, Quality Manual | A, B, C, D, F |
| | Refurbishment and demolition survey: (domestic, commercial and industrial premises) | Documented in-house procedure - Inspection, section 20 and appendix 6, Quality Manual | A, B, C, D, F |
| | Re-inspection of identified or suspected asbestos containing material in surveyed premises | Documented in-house procedure - Inspection, section 20 and appendix 6, Quality Manual (based on guidance documented in Inspection, Appendix 5 of HSG 227 (2004)) | A, B, C, D, F |
| END | | | |