Schedule of Accreditation

issued by

United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK



0291 Type C Inspection Body

B63 3US

Accredited to ISO/IEC 17020:2012

Bradley Environmental Consultants Ltd

Issue No: 015 Issue date: 22 September 2021

20 Stourbridge Road Contact: Mr R Bridgewater
Halesowen Tel: +44 (0)121 550 0224

West Midlands Fax: +44 (0)121 550 0641

E-Mail: rbridgewater@bradley-enviro.co.uk

Website: www.bradley-enviro.co.uk

Inspection performed at/from the locations specified below

Locations covered by the organisation and their relevant activities

Location details		Activity	Location code
Address 20 Stourbridge Road Halesowen West Midlands B63 3US	Local contact Mr R Bridgewater Tel: +44 (0)121 550 0224 Fax: +44 (0)121 550 0641 Email: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	Support Functions: Quality Management including document control, auditing and quality control Asbestos: Surveying	A
Address Parkway House Wakefield Road Ossett West Yorkshire WF5 9JD	Local contact Mr R Bridgewater Tel: +44 (0)1924 274777 Fax: +44 (0)1924 283620 Email: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	Asbestos: Surveying	В
Address North West Office Constellation House Lockheed Court Amy Johnson Way Blackpool FY4 2RN	Local contact Mr R Bridgewater Tel: +44 (0)1253 405396 Fax: +44 (0)1253 402426 Email: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	Asbestos: Surveying	С
Address 85A Bowen Court St Asaph Business Park St Asaph LL17 0JE	Local contact Mr R Bridgewater Tel: +44 (0) 1745 585587 Fax: +44 (0) 1745 584974 E-Mail: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	Asbestos: Surveying	D

Assessment Manager: RC1 Page 1 of 3



0291 Type C Inspection Body

Accredited to ISO/IEC 17020:2012

Schedule of Accreditation issued by **United Kingdom Accreditation Service**

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

Bradley Environmental Consultants Ltd

Issue No: 015 Issue date: 22 September 2021

Inspection performed by the Organisation at/from the locations specified

Address Unit 16 Geddes House Kirkton Road North Livingston EH54 6GU

Local contact Mr R Bridgewater

Tel: +44 (0)1745 585587

Fax: +44 (0) 1745 584974 E-Mail: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk

Hygiene and Health

F

Assessment Manager: RC1 Page 2 of 3



0291 Type C Inspection Body

Accredited to ISO/IEC 17020:2012

Schedule of Accreditation issued by United Kingdom Accreditation Service 2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

Bradley Environmental Consultants Ltd

Issue No: 015 Issue date: 22 September 2021

Inspection performed by the Organisation at/from the locations specified

DETAIL OF ACCREDITATION

Field of Inspection	Type and Range of Inspection	Methods and Procedures	Location Code
Surveying for asbestos in premises		Health and Safety Executive Asbestos: The survey guide (HSG 264:2012)	
	Management survey: (domestic, commercial and industrial premises)	Documented in-house procedure - Inspection, section 20 and appendix 6, Quality Manual	A, B, C, D, F
	Refurbishment and demolition survey: (domestic, commercial and industrial premises)	Documented in-house procedure - Inspection, section 20 and appendix 6, Quality Manual	A, B, C, D, F
	Re-inspection of identified or suspected asbestos containing material in surveyed premises	Documented in-house procedure - Inspection, section 20 and appendix 6, Quality Manual (based on guidance documented in Inspection, Appendix 5 of HSG 227 (2004))	A, B, C, D, F
	END		1

Assessment Manager: RC1 Page 3 of 3