

United Kingdom Accreditation Service

ACCREDITATION CERTIFICATE



**INSPECTION BODY
No. 0291**

Bradley Environmental Consultants Ltd

is accredited as a Type C body in accordance with the recognised International Standard ISO/IEC 17020:2012 - Conformity assessment – Requirements for the operation of various types of bodies performing inspection.

This accreditation demonstrates technical competence for a defined scope as detailed in and at the locations specified in the schedule to this certificate.

The schedule to this certificate is an essential accreditation document and from time to time may be revised and reissued by the United Kingdom Accreditation Service. The most recent issue of the schedule of accreditation, which bears the same accreditation number as this certificate, is available from the UKAS website www.ukas.com.

This accreditation is subject to continuing conformity with United Kingdom Accreditation Service requirements. The absence of a schedule on the UKAS website indicates that the accreditation is no longer in force.



Accreditation Manager, United Kingdom Accreditation Service

**Initial Accreditation date
3 September 2004**

**This certificate issued on
13 January 2015**


UKAS is appointed as the sole national accreditation body for the UK by The Accreditation Regulations 2009 (SI No 3155/2009) and operates under a Memorandum of Understanding (MoU) with the Department for Business, Innovation and Skills (BIS).

Schedule of Accreditation

issued by

United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

 <p>0291 Type C Inspection Body</p> <p>Accredited to ISO/IEC 17020:2012</p>	Bradley Environmental Consultants Ltd	
	Issue No: 014 Issue date: 22 February 2016	
20 Stourbridge Road Halesowen West Midlands B63 3US	Contact: Mr R Bridgewater Tel: +44 (0)121 550 0224 Fax: +44 (0)121 550 0641 E-Mail: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	
Inspection performed at/from the locations specified below		

Locations covered by the organisation and their relevant activities

Location details	Activity	Location code	
Address 20 Stourbridge Road Halesowen West Midlands B63 3US	Local contact Mr R Bridgewater Tel: +44 (0)121 550 0224 Fax: +44 (0)121 550 0641 Email: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	Support Functions: Quality Management including document control, auditing and quality control Asbestos: Surveying	A
Address Parkway House Wakefield Road Ossett West Yorkshire WF5 9JD	Local contact Mr R Bridgewater Tel: +44 (0)1924 274777 Fax: +44 (0)1924 283620 Email: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	Asbestos: Surveying	B
Address North West Office Constellation House Lockheed Court Amy Johnson Way Blackpool FY4 2RN	Local contact Mr R Bridgewater Tel: +44 (0)1253 405396 Fax: +44 (0)1253 402426 Email: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	Asbestos: Surveying	C
Address 85A Bowen Court St Asaph Business Park St Asaph LL17 0JE	Local contact Mr R Bridgewater Tel: +44 (0) 1745 585587 Fax: +44 (0) 1745 584974 E-Mail: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	Asbestos: Surveying	D



0291

Type C
Inspection Body

Accredited to
ISO/IEC 17020:2012

Schedule of Accreditation
issued by
United Kingdom Accreditation Service
2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

Bradley Environmental Consultants Ltd
Issue No: 014 Issue date: 22 February 2016

Inspection performed by the Organisation at/from the locations specified

DETAIL OF ACCREDITATION

Field of Inspection	Type and Range of Inspection	Methods and Procedures	Location Code
Surveying for asbestos in premises	Management survey: (domestic, commercial and industrial premises)	Health and Safety Executive Asbestos: The survey guide (HSG 264:2012) Documented in-house procedure - Inspection, section 20 and appendix 6, Quality Manual	A, B, C, D
	Refurbishment and demolition survey: (domestic, commercial and industrial premises)	Documented in-house procedure - Inspection, section 20 and appendix 6, Quality Manual	A, B, C, D
	Re-inspection of identified or suspected asbestos containing material in surveyed premises	Documented in-house procedure - Inspection, section 20 and appendix 6, Quality Manual (based on guidance documented in Inspection, Appendix 5 of HSG 227 (2004))	A, B, C, D
END			