


Schedule of Accreditation

issued by

United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

 <p>0291 Type C Inspection Body</p> <p>Accredited to ISO/IEC 17020:2012</p>	Bradley Environmental Consultants Ltd	
	Issue No: 014 Issue date: 22 February 2016	
20 Stourbridge Road Halesowen West Midlands B63 3US	Contact: Mr R Bridgewater Tel: +44 (0)121 550 0224 Fax: +44 (0)121 550 0641 E-Mail: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	
Inspection performed at/from the locations specified below		

Locations covered by the organisation and their relevant activities

Location details	Activity	Location code
Address 20 Stourbridge Road Halesowen West Midlands B63 3US Local contact Mr R Bridgewater Tel: +44 (0)121 550 0224 Fax: +44 (0)121 550 0641 Email: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	<u>Support Functions:</u> Quality Management including document control, auditing and quality control <u>Asbestos:</u> Surveying	A
Address Parkway House Wakefield Road Ossett West Yorkshire WF5 9JD Local contact Mr R Bridgewater Tel: +44 (0)1924 274777 Fax: +44 (0)1924 283620 Email: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	<u>Asbestos:</u> Surveying	B
Address North West Office Constellation House Lockheed Court Amy Johnson Way Blackpool FY4 2RN Local contact Mr R Bridgewater Tel: +44 (0)1253 405396 Fax: +44 (0)1253 402426 Email: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	<u>Asbestos:</u> Surveying	C
Address 85A Bowen Court St Asaph Business Park St Asaph LL17 0JE Local contact Mr R Bridgewater Tel: +44 (0) 1745 585587 Fax: +44 (0) 1745 584974 E-Mail: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	<u>Asbestos:</u> Surveying	D



0291
Type C
Inspection Body
 Accredited to
 ISO/IEC 17020:2012

Schedule of Accreditation
 issued by
United Kingdom Accreditation Service
 2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

Bradley Environmental Consultants Ltd
Issue No: 014 Issue date: 22 February 2016

Inspection performed by the Organisation at/from the locations specified

DETAIL OF ACCREDITATION


Field of Inspection	Type and Range of Inspection	Methods and Procedures	Location Code
Surveying for asbestos in premises	Management survey: (domestic, commercial and industrial premises)	Health and Safety Executive Asbestos: The survey guide (HSG 264:2012) Documented in-house procedure - Inspection, section 20 and appendix 6, Quality Manual	A, B, C, D
	Refurbishment and demolition survey: (domestic, commercial and industrial premises)	Documented in-house procedure - Inspection, section 20 and appendix 6, Quality Manual	A, B, C, D
	Re-inspection of identified or suspected asbestos containing material in surveyed premises	Documented in-house procedure - Inspection, section 20 and appendix 6, Quality Manual (based on guidance documented in Inspection, Appendix 5 of HSG 227 (2004))	A, B, C, D
END			

Schedule of Accreditation

issued by

United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

 <p>UKAS TESTING 1155</p> <p>Accredited to ISO/IEC 17025:2005</p>	Bradley Environmental Consultants Ltd	
	Issue No: 029 Issue date: 20 October 2016	
20 Stourbridge Road Halesowen West Midlands B63 3US	Contact: Mr R Bridgewater Tel: +44 (0)121 550 0224 Fax: +44 (0)121 550 0641 E-Mail: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	
Testing performed by the Organisation at the locations specified below		

Locations covered by the organisation and their relevant activities

Laboratory locations:

Location details	Activity	Location code	
Address 20 Stourbridge Road Halesowen West Midlands B63 3US	Contact: Mr R Bridgewater Tel: +44 (0)121 550 0224 Fax: +44 (0)121 550 0641 E-Mail: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	Support functions: Quality System support Quality audit administration Hygiene and Health	A
Address Parkway House Wakefield Road Ossett West Yorkshire WF5 9JD	Local contact Mr R Bridgewater Tel: +44 (0)1924 274777 Fax: +44 (0)1924 283620 Email: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	Hygiene and Health	B
Address Constellation House Shorebury Point Amy Johnson Way Blackpool FY4 2RN	Local contact Mr R Bridgewater Tel: +44 (0)1253 405396 Fax: +44 (0)1253 402426 E-Mail: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	Hygiene and Health	C
Address 85A Bowen Court St Asaph Business Park St Asaph LL17 0JE	Local contact Mr R Bridgewater Tel: +44 (0)1745 585587 Fax: +44 (0) 1745 584974 E-Mail: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	Hygiene and Health	D



1155

Accredited to
ISO/IEC 17025:2005

Schedule of Accreditation
issued by
United Kingdom Accreditation Service
2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

Bradley Environmental Consultants Ltd
Issue No: 029 Issue date: 20 October 2016

Testing performed by the Organisation at the locations specified

Site activities performed away from the locations listed above:

Location details	Activity	Location code
Premises including domestic, commercial and industrial	Hygiene and Health	Halesowen - AS Ossett - BS Blackpool - CS St Asaph - DS
Mobile Laboratories	Hygiene and Health	E



1155
Accredited to
ISO/IEC 17025:2005

Schedule of Accreditation
issued by
United Kingdom Accreditation Service
2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

Bradley Environmental Consultants Ltd
Issue No: 029 Issue date: 20 October 2016

Testing performed by the Organisation at the locations specified

DETAIL OF ACCREDITATION

Materials/Products tested	Type of test/Properties measured/Range of measurement	Standard specifications/ Equipment/Techniques used	Location Code
ASBESTOS FIBRES IN AIR	<u>Health and Hygiene</u>	Health and Safety Executive Asbestos: The analysts' guide for sampling, analysis and clearance procedures (HSG 248)	
	Sampling of air for fibre counting	HSG 248:February 2005 Documented in-house procedure, appendix 6, Quality Manual	AS, BS, CS, DS, E
	Fibre counting	HSG 248:February 2005 Documented in-house procedure, appendix 6, Quality Manual Membrane filter method using Phase Contrast Microscopy (PCM)	A, B, C, D, AS, BS, CS, DS, E
ASBESTOS IN BULK MATERIALS including materials and products suspected of containing asbestos	4 Stage Clearance Process	HSG 248:February 2005 Documented in-house procedure, appendix 6, Quality Manual Membrane filter method using Phase Contrast Microscopy (PCM)	AS, BS, CS, DS, E
	Sampling of bulk materials for asbestos identification	HSG 248:February 2005 (Documented in-house procedure, appendix 6, Quality Manual)	AS, BS, CS, DS, E
	Identification of: Amosite Chrysotile Crocidolite Fibrous Actinolite Fibrous Anthophyllite Fibrous Tremolite	HSG 248:February 2005 Documented in-house procedure, appendix 7, Quality Manual, using stereo-microscopy, polarised light microscopy, dispersion staining and phase contrast	A, B, C, D
END			